N.

N. HURO

YPSILANTI DRESS STAY M'F'G. CO.
WELL & PUMP IN B'LD'G.
WATCHMAN. HEAT: STOVES. FUEL: COAL & GAS
LIGHTS: GAS. 125 HANDS.

231 232

50'

PINKING & CEMENTING & PACKING.

W.R'M. -&- OFF.

WELL & PUMP.

GAS ENG. 10 H.P.

WINDOW

BRIDGE 2a

Y.O.S. MF'G. CO.

TIN SHOP.

210.

209½

209

233 234 235 236

PHOTO. 2a

P.O.

SKY LIGHT.

Books. OFFS. 2a

Gro.

DRS. OFF. 2a

Jewelry.

220.

236½

NOT USED.

DRIVE.

GLASS.

OVEN.

219

OFF.